

Palmer Ag Nozzle Selection Chart

Part Number	Tip Color	Tip Size	PSI	kPa	L/min 1 tip	L/min 2 tips
6500033	SS	0.33	15	100	0.07	0.15
<i>*Use with small square baler only</i>			20	135	0.10	0.19
			25	170	0.11	0.21
			30	200	0.11	0.23
			35	235	0.12	0.25
			40	270	0.13	0.26
1100050	SS	0.5	15	100	0.09	0.18
			20	135	0.13	0.26
			25	170	0.15	0.29
			30	200	0.16	0.33
			35	235	0.18	0.35
			40	270	0.19	0.38
1100067	Olive/SS	0.67	15	100	0.15	0.30
			20	135	0.19	0.39
			25	170	0.21	0.43
			30	200	0.23	0.45
			35	235	0.25	0.49
			40	270	0.26	0.52
11001	Orange	1	15	100	0.23	0.45
			20	135	0.27	0.54
			25	170	0.30	0.61
			30	200	0.34	0.67
			35	235	0.36	0.72
			40	270	0.39	0.79
110015	Green	1.5	15	100	0.36	0.72
			20	135	0.43	0.85
			25	170	0.47	0.94
			30	200	0.52	1.03
			35	235	0.54	1.09
			40	270	0.57	1.15

This handout is provided to you by
Palmer Ag



Palmer Ag Nozzle Selection Chart

Part Number	Tip Color	Tip Size	PSI	kPa	L/min 1 tip	L/min 2 tips
11002	Yellow	2	15	100	0.44	0.88
			20	135	0.53	1.06
			25	170	0.59	1.19
			30	200	0.65	1.30
			35	235	0.71	1.43
			40	270	0.77	1.54
11003	Blue	3	15	100	0.68	1.36
			20	135	0.80	1.60
			25	170	0.87	1.74
			30	200	0.98	1.96
			35	235	1.05	2.09
			40	270	1.12	2.25
11004	Red	4	15	100	0.91	1.83
			20	135	1.07	2.13
			25	170	1.21	2.42
			30	200	1.33	2.66
			35	235	1.42	2.84
			40	270	1.51	3.02
11005	Brown	5	15	100	1.19	2.37
			20	135	1.33	2.66
			25	170	1.48	2.95
			30	200	1.63	3.26
			35	235	1.77	3.55
			40	270	1.89	3.79
11006	Gray	6	15	100	1.39	2.78
			20	135	1.60	3.19
			25	170	1.77	3.55
			30	200	1.98	3.96
			35	235	2.13	4.26
			40	270	2.28	4.55

This handout is provided to you by
Palmer Ag

